



M=1:4000

10 11
13* 13

11 12
13 14

K eü ²	SZ	10	60
	7.5°	10000	5000

Üh ⁴	SZ	10	60
	7.5°	1000	550

K st ¹	SZ	10	60
	4.5°	1000	550

Üh ¹	SZ	10	60
	7.5°	10000	5000

Üh ³	SZ	10	60
	7.5°	1000	550

Üh ^{3*}	SZ	10	60
	7.5°	1000	550

K st ¹	SZ	10	60
	4.5°	1000	550

Vg tómeder

Vg tómeder

13* 13